

The cylindrical part removed and
The PCB is accessible for repair.



There is no need to remove the
Connector.